

Appendix – Freeze Thaw Images



Sample 1A, 100 Cycles, Polyarmor G17



Sample 1B, 100 Cycles, Polyarmor G17

Appendix – Freeze Thaw Images



Sample 2A, 100 Cycles, Polyarmor G17



Sample 2B, 100 Cycles, Polyarmor G17

Appendix – Freeze Thaw Images



Sample 3A, 100 Cycles, Polyarmor G17



Sample 3B, 100 Cycles, Polyarmor G17

Appendix – Freeze Thaw Images



Sample 4A, 100 Cycles, Carboline 858 & Polyarmor G17



Sample 4B, 100 Cycles, Carboline 858 & Polyarmor G17

Appendix – Freeze Thaw Images



Sample 5A, 100 Cycles, Carboline 858 & Polyarmor G17



Sample 5B, 100 Cycles, Carboline 858 & Polyarmor G17

Appendix – Freeze Thaw Images



Sample 6A, 100 Cycles, Carboline 858 & Polyarmor G17



Sample 6A, 100 Cycles, Carboline 858 & Polyarmor G17

Appendix – Freeze Thaw Images



Sample 7A, 100 Cycles, Valspar EEG 70% Zinc & TCI RAL 7037 Polyester



Sample 7B, 100 Cycles, Valspar EEG 70% Zinc & TCI RAL 7037 Polyester

Appendix – Freeze Thaw Images




Sample 8B, 100 Cycles, Carbolite 858 & Pipe Clad 2000 Epoxy



Sample 8B, 100 Cycles, Carbolite 858 & Pipe Clad 2000 Epoxy

Appendix – Freeze Thaw Images




Sample 9B, 100 Cycles, Trenchcoat over galvanized



Sample 9B, 100 Cycles, Trenchcoat over galvanized

Appendix – Freeze Thaw Images



Sample 10A, 100 Cycles, Trenchcoat over galvanized



Sample 10B, 100 Cycles, Trenchcoat over galvanized

Appendix – Freeze Thaw Images



Sample 11A, 100 Cycles, Trenchcoat over galvanized



Sample 11B, 100 Cycles, Trenchcoat over galvanized

Appendix – Freeze Thaw Images



Sample 12A, 100 Cycles, Trenchcoat over galvanized



Sample 12B, 100 Cycles, Trenchcoat over galvanized