

San Benito, California

DIAMETER	GAGE	YEAR INSTALLED	INSPECTION DATE
30" - RIVETED	14 (0.079 IN)	ESTIMATED 1952	NOVEMBER, 2012
PROFILE	COATING	SOIL DATA	WATER DATA
2 2/3 X 1/2	ALUMINIZED TYPE 2	PH: 5.1	PH: DRY
		RESISTIVITY: 630 Ω-CM	RESISTIVITY: DRY
			FHWA ABRASION LEVEL: 1
			CHLORIDES: DRY
			CaCO ₃ : DRY

IMAGES:



ULTRA-SONIC PIPE THICKNESS (IN):

- INVERT: AVG = 0.070 (0.070, 0.071, 0.068, 0.072)
*Measured using TI-25M Ultrasonic Wall Thickness Gauge

COMMENTS:

- Did not appear to be any coating remaining at the invert
- No pavement distress
- Local property owner says they work well